



# Notice Of Modification



No. 2015-03	Photo / drawing present situation
Date: January 2015	
Description: O-ring for mounting suction tube # 0065734 has been replaced by # 0065786 (P 2-75/85/95)  # 0065736 has been replaced by # 0065788 (Falcon series / Polar 2-40/50)	
Modification applies to model(s):	
Falcon 2-60 / 2-70	
Polar 2-40 / 2-50 / 2-75 / 2-85 / 2-95	

Present part still available: No, the O-rings can be interchanged. Old ones will not be available anymore
New part number: # 0065786    Polar 2-75 / 2-85 / 2-95 # 0065788    Falcon 2-60 / 2-70 / Polar 2-40 / 2-50
New part number one on one interchangeable: <b>Yes</b>
Mentioned modification is valid from: January 2015

Reason of modification:

To avoid damage to the black mounting blocks.  
 The O-ring is only needed to avoid the V-ring for becoming flat.  
 By using a smaller O-ring, there is less friction between the suction tube and the mounting blocks and still avoids the lip to become flat