


COMPLETE MOTOR

**HOLE TO FIX
FLANGE TO
OVEN REAR**

**MOTOR DELIVERED AS SPARES
PART MISSES THE HOLE TO FIX
FLANGE TO MOTOR BODY. ONLY
HOLES FOR OVEN FLANGE FIXING**

**IF POSSIBLE, DISMANTLE THE ORIGINAL FLANGE AND MOUNT IT ON
THE NEW MOTOR, OTHERWISE DRILL OUT THE MISSING HOLE ON
THE NEW PART**

BUSHINGS TO FIX THE FLANGE ARE NOT INCLUDED IN THE SPARE PART CODE. ORDER 3 PIECES PARTNO. 180570136



DETAIL OF BUSHING PARTNO 180570136