

TECHNISCHE INFORMATION HINWEIS TECHNICAL INFORMATION NOTE FREQUENZUMRICHTER / VARIABLE FREQUENCY DRIVE

Sehr geehrte Damen und Herren,

Heute informieren wir Sie über einen möglichen Defekt am Widerstand im Frequenzumrichter.

Für folgende Geräte:

- R402 V.V. R502 V.V. R602 V.V. R652 V.V.
- R4 V.V. R5 V.V. R6V.V.
- Blixer 4 V.V. Blixer 5 V.V Blixer 6 V.V
- Robot Cook

Die zugehörigen Teilenummern der betroffenen Laufwerke sind:

39630, 39678,39972,39974,39975,39976

Die Anzahl der tatsächlichen Reklamation ist minimal und das Risiko eines auftretenden Fehlers sehr gering.

We have identified a potential defect on a resistor used on our variable frequency drive mounted on the following models:


- R402 V.V. R502 V.V. R602 V.V. R652 V.V.
- R4 V.V. R5 V.V. R6V.V.
- Blixer 4 V.V. Blixer 5 V.V Blixer 6 V.V
- Robot Cook

The related part numbers of the concerned drives are:

39630, 39678,39972,39974,39975,39976

By the effect of successive power up (action to insert the plug attachment into the socket) over a short period, this resistance may become fragile and break.

The consequence is a failure of the drive. It cannot be powered anymore, it does not work any longer. The drive is however repairable by our services. This defect may relate only to the drives with serial numbers in the following ranges:

Von From	Zu To	Lesen der Seriennummer des Laufwerks Reading of the Serial Number of the drive
1901 0326	1901 0600	
1902 0601	1902 0924	
1903 1516	1903 1800	
1903 1801	1903 2100	
1904 2101	1904 2112	
1904 2113	1904 2399	
1905 2701	1905 3012	

Gleichwohl möchten wir Sie hierüber im Vorfeld proaktiv informieren. Für den Fall, dass bei besagten Geräten ein Fehler auftritt, tauschen wir das entsprechende Bauteil gerne kostenlos aus.

Sollten Sie hierzu noch Fragen haben, stehen wir Ihnen selbstverständlich jederzeit gerne zur Verfügung.

Of course, we will take over all the drives concerned under warranty, provided that we **have in return the defective or potentially defective part.**

Today, **the failure rate observed is very low and the risk of failure minimal**, but we wanted to share this information with you as a precaution.

Robot Coupe remains at your disposal for any request for additional information